

LEXUS VEHICLES AFFECTED BY ACTIVE TAKATA RECALL CAMPAIGN					
INVOLVED AIRBAG	ALPHA or BETA	MODELS INVOLVED	PRA NUMBER ¹	PRODUCTION RANGE	
PASSENGER FRONT AIRBAG INFLATOR	ALPHA	SC430 UZZ40 FN48Y	2013/13545	Dec 2000 through May 2003	
	BETA	SC430 UZZ40 FN48Y	2015/14795	June 2003 through July 2007	
		SC430 UZZ40 FN45Y	2015/14795	Aug 2006 through June 2010	
		LFA	2017/15846	Feb 2011 through June 2012	
		IS250	2016/15425	Aug 2005 through Dec 2011	
			2017/15846	Jan 2012 through Dec 2012	
			2018/16536	Jan 2013 through Mar 2013	
		IS350	2016/15425	Aug 2010 through Dec 2012	
			2017/15846	Jan 2012 through Dec 2012	
			2018/16536	Jan 2013 through Mar 2013	
		IS-F	2016/15425	7 Aug 2008 through 26 Dec 2012	
			2017/15846	Jan 2012 through Dec 2012	
			2018/16536	Jan 2013 through Dec 2013	
		IS250C	2016/15425	April 2009 through Nov 2011	
			2017/15846	Jan 2012 through Dec 2012	
			2018/16536	Jan 2013 through Dec 2013	
		LIKE FOR LIKE	SC430 UZZ40 FN45Y, FNY48Y	2018/17147 2019/17787	Aug 2001 through Jun 2010

* Although the involved vehicles are within the above production ranges, not all vehicles in these production ranges were sold in the Australian market.

1. Some of these vehicles may have more than one Takata recall campaign PRA number associated with them. If yes, then only the most recent Takata recall campaign PRA number applies to that Lexus vehicle. For example, some vehicles in campaign PRA 2018/17147 were previously repaired by replacing the affected Takata airbags with new Takata non-desiccated airbags ('like for like' airbags) under PRA 2015/14795. This was to secure immediate safety in the face of parts supply challenges globally. To ensure long-term safety, the replacement airbags are now being replaced again under PRA 2018/17147 with desiccated Takata airbags or alternate

supplier airbags (i.e. not with a 'like for like' airbag).